





8C22-100
DINGS' MOTION
Work order
DATE REV00

REVISION

REV.	DATE	DESCRIPTION	DRAWN BY
------	------	-------------	----------




Motor's phase	2
Step angle(±5%)	1.8°
Rated current/phase	--A(RMS)
Resistance/phase(20°C)	--Ω±10%
Inductance/phase(1V,1kHz)	--mH±20%
Linear travel per step	--mm/step
Lead screw diameter	Ø 3.5mm
Lead screw lead	--mm
Nut material	--
Insulation class	B
Insulation resistance	100MΩ(500VDC)
Heat rise	80°C
Motor weight	0.08 kg
Thrust	--
Stroke	25.4mm

Notes,

1.To maximize output force and life of linear actuators,
radial load on lead screws should be avoided or be kept at a minimum.

CUSTOMER

WIRING CHART



EXCITATION SEQUENCE

CW	→
Red A+	+
Red/Wht A-	-
Grn B+	+
Grn/Wht B-	-
CCW	←

NOTICE TO PERSONS RECEIVING THIS DRAWING
THIS DRAWING IS ONLY CONDITIONALLY ISSUED, AND FOR THE SOLE PURPOSE OF INFORMING LICENSEES AND ASSOCIATE CONTRACTORS OF DINGS' MOTION, AND VENDORS THERE TO AND CUSTOMERS THERE OF.
RECEIPT OR POSSESSION THEREOF DOES NOT CONFER TO TRANSFER ANY RIGHT IN THE SUBJECT MATTER OF THE DRAWING, THE DESIGN, CONSTRUCTION, TECHNICAL INFORMATION AND ALL OTHER SUBJECT MATTER
SHOWN AND ASSOCIATE CONTRACTORS OF SAID CORPORATION AND ONLY FOR LICENSED MANUFACTURE, AND BY VENDORS MANUFACTURING FOR SAID CORPORATION AND ONLY FOR LICENSEES AND
ASSOCIATE CONTRACTORS.



UNLESS OTHERWISE SPECIFIED ALL
DIMENSIONS ARE IN MILLIMETERS AND
TOLERANCES ARE AS BELOW PER ISO2768-cK.

LINEAR		ANGULAR	
0 ~ 3	±0.2	0 ~ 10	±15°
3 ~ 6	±0.5	10 ~ 50	±30°
6 ~ 30	±0.8	50 ~ 120	±1°
30 ~ 120	±1.5	120 ~ 400	±1.5°

DRAWN

DATE

APPRVD

DATE

MODEL

8C22-100

DINGS'

SIZE	A3	SHEET	1 OF 1
SCALE	1 : 1	REV	00

